SECTION X

REINSPECTION AND PERIODIC SURVEILLANCE PLAN

X-A PLAN FOR BUILDING REINSPECTION (763.85 b)

At least once every three (3) years after the Management Plan is in effect (time of delivery to school Principal), the District shall conduct a reinspection of all friable and nonfriable known or assumed asbestos containing building material.

In an effort to comply with the reinspection date, the Asbestos Office has developed a computerized "time-task calendar" in which the computer shall generate an appropriate date to meet the three year mandatory time frame. Daily management of the time-task calendar shall notify the Management Planner in a timely manner when the reinspection should be accomplished.

X-B PLAN FOR ASBESTOS OPERATIONS AND MAINTENANCE ACTIVITIES (763.91)

The Districts in-house asbestos crew has already implemented; and shall continue to maintain, an operations, maintenance, and repair (O&M) program if feasible, whenever any friable ACBM was present or assumed to be present.

The Operations and Maintenance program is generated by the custodial work order system as previously defined.

The user of this Document may use the individual "room survey forms" found in Section IV, Management Plan/Operation and Maintenance Section, to find whether past work was performed in a room or if future work shall be scheduled.

X-C PLAN FOR PERIODIC SURVEILLANCE AND REPORTING (763.92 b) (763.94 d,e)

The District shall conduct, at least once every 6 months, a periodic surveillance of each school that has been inspected. The surveillance shall

consist of visually inspecting all areas that are identified in this Management Plan as containing ACBM or assumed ACBM. A record of the date of the surveillance, inspectors name, and any changes in the material since the last inspection or surveillance.

Upon completion of the surveillance, the Asbestos Program Manager shall carry out the Districts responsibilities under 763.84 and send a copy of such record for inclusion to this Management Plan.

The scheduling of the surveillance shall be identified by the "time-task calendar" and shall indicate by a computer spread sheet when a 6 month surveillance of this building should be completed.

X-D PLAN FOR MODIFIED CLEANING PROCEDURES (763.91 c)

The District is prepared to perform recommended cleaning of all areas of the school building where friable ACBM, damaged or significantly damaged thermal insulation, or friable suspected ACBM is present. Cleaning shall be performed before the initiation of any response action scheduled on "survey forms" in Section IV.

ATTACHMENT XV

PERIODIC SURVEILLANCE REPORT

Project No. #058

Date of Report 2-22-89

1st surveillance

Building Name Brooklawn Elementary

Address 11801 Worthington Ave.

City/State/Zip Cleveland, Ohio 44111

Person Completing Report:

Name Frank Geraci #3883 Signature [signature]

Person Recommending Response:

Name _____ Signature _____

Title _____ State _____ Certificate No. _____

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report	Change		If Yes	Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	Yes	No	DC	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																	No noticable changes in ACBM or assumed ACBM.

Type of Material:
- S - Surfacing
- T - Thermal Insulation
- M - Miscellaneous

Damage Condition (DC):
- ND - No Damage
- D - Damage
- SD - Significant Damage

Recommended Response:
- Cl. - Clean
- Enc. - Encapsulate
- Encl. - Enclose
- Rem. - Remove & Replace
- Rep. - Repair

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058

BUILDING NAME Brooklawn

ADDRESS 11801 Worthington

CITY/STATE/ZIP Cleveland, OH 44111

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
FRED R. LA MALFA
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

DATE OF REPORT 9-7-89

2nd surveillance

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:

NAME Frank Geraci SIGNATURE [signature]

TITLE Evaluation Specialist STATE Ohio

CERTIFICATE NUMBER 3883

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticeable changes in ACBM or assumed ACBM.

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058
BUILDING NAME Brooklawn Elementary
ADDRESS 11801 Worthington
CITY/STATE/ZIP Cleveland, Ohio 44111

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
FRED R. LA MALFA
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

DATE OF REPORT 4-12-90
3rd surveillance

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:
NAME Frank Geraci SIGNATURE [signature]
TITLE Evaluation Specialist STATE Ohio
CERTIFICATE NUMBER 3883

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticeable changes in ACBM or assumed ACBM except for:
BSMT	Boiler Room		X		Pipe Ins.	D	1	X		ND	0			X				X	Req. #51056
BSMT	Boiler Room		X		Pipe Joint	D	1	X		ND	0			X				X	Req. #51056
BSMT	Boiler Room		X		Boiler Ins.	D	5	X		ND	0			X				X	Req. #51056

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058
BUILDING NAME Brooklawn Elementary
ADDRESS 11801 Worthington Avenue
CITY/STATE/ZIP Cleveland, Ohio 44111

DATE OF REPORT 1-10-91
4th Surveillance

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
FRED R. LA MALFA
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:
NAME Frank Geraci SIGNATURE Frank Geraci
TITLE Evaluation Specialist STATE Ohio
CERTIFICATE NUMBER #3883

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticeable changes in ACBM or assumed ACBM.

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058

BUILDING NAME Brooklawn Elementary

ADDRESS 11801 Worthington Avenue

CITY/STATE/ZIP Cleveland, Ohio 44111

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
FRED R. LA MALFA
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

DATE OF REPORT 8-9-91
5th Surveillance

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:

NAME Frank Geraci SIGNATURE

TITLE Evaluation Specialist STATE Ohio

CERTIFICATE NUMBER #3883

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticeable changes in ACBM or assumed ACBM.

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058
BUILDING NAME Brooklawn Elementary
ADDRESS 11801 Worthington Ave.
CITY/STATE/ZIP Cleveland, Ohio 44111

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
FRED R. LA MALFA
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

DATE OF REPORT 3-26-92
6th Re-Inspection

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:
NAME Fred La Malfa Jr. SIGNATURE Fred La Malfa Jr.
TITLE Evaluation Specialist STATE Ohio
CERTIFICATE NUMBER #3882

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticeable changes in ACBM or assumed ACBM except for:
BSMT	Boiler Room (BORM) (BRRM)				Pipe Ins.	ND	0	X		D	1	X		X				X	
			X		Pipe Joint	ND	0	X		D	1	X		X				X	

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school.
Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058
BUILDING NAME Brooklawn Elementary
ADDRESS 11801 Worthington Avenue
CITY/STATE/ZIP Cleveland, Ohio 44111

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
FRED R. LA MALFA
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

DATE OF REPORT 10-29-92
7th Surveillance

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:
NAME Fred La Malfa Jr. SIGNATURE Fred La Malfa
TITLE Evaluation Specialist STATE Ohio
CERTIFICATE NUMBER #3882

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticeable changes in ACBM or assumed ACBM except for:
1st	Classroom 117 (0117)			X	Floor Tile									X			X		Minor cracks in floor tile due to floor settling.
1st	Corridor "A" (CDRA)			X	Floor Tile									X			X		Minor cracks in floor tile due to floor settling.

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school.
Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058

BUILDING NAME Brooklawn Elementary

ADDRESS 11801 Worthington Ave.

CITY/STATE/ZIP Cleveland, O

DATE OF REPORT 12/2/93

8th Surveillance

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
FRED R. LA MALFA
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

No appointment has been made since Mr. La Malfa retired on 6/1/93

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:

NAME Richard Malott SIGNATURE Richard Malott

TITLE Asbestos Foreman STATE Ohio

CERTIFICATE NUMBER 3012

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticeable changes in ACBM or assumed ACBM

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. 058

BUILDING NAME BROOKLAWN ELEMENTARY

ADDRESS 11801 WORTHINGTON AVE

CITY/STATE/ZIP CLEVELAND, O.

DATE OF REPORT 8/23/94

4TH SURVEILLANCE

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON

Richard Malott
3840 Ridge Rd
Cleveland, Ohio 44144
634-7111

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:

NAME RICHARD MALOTT SIGNATURE [signature]

TITLE EVAL. SPEC. STATE OHIO

CERTIFICATE NUMBER 3012

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			NO NOTICABLE CHANGES IN ACBM OR ASSUMED ACBM
																			EXCEPT:
																			W.O. #80122 - REMOVAL OF
																			3' OF TSI (ACBM) FROM
																			H_2O SUPPLY VALVE LOCATED
																			IN BOILER ROOM

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (PE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. 058

BUILDING NAME BROOKLAWN ELEMENTARY

ADDRESS 11801 WORTHINGTON

CITY/STATE/ZIP CLEVELAND, O.

DATE OF REPORT 5/31/95

10TH SURVEILLANCE

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON

Richard Malott
3840 Ridge Rd
Cleveland, Ohio 44144
634-7111

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:

NAME RICHARD MALOTT SIGNATURE Rich Malott

TITLE EVALUATION SPECIALIST STATE OHIO

CERTIFICATE NUMBER 3012

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No changes in ACBM or assumed ACBM

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (PE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. 058
BUILDING NAME Brooklawn Elem
ADDRESS 11801 Northrup
CITY/STATE/ZIP Cleveland

DATE OF REPORT 1/30/96
11TH Surveillance

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON

Richard Malott
3840 Ridge Rd
Cleveland, Ohio 44144
634-7111

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:

NAME RICHARD MALOTT SIGNATURE [signature]

TITLE EVALUATION SPECIALIST STATE OHIO

CERTIFICATE NUMBER 3012

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No changes in ACBM or assumed ACBM

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (PE-INSPECTION & PERIODIC SURVEILLANCE).

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

DATE OF REPORT 8/28/96
12TH SURVEILLANCE

ECT NO. 058
DING NAME BROOKLAWN ELEM
ESS 11801 WORTHINGTON
/STATE/ZIP CLEVELAND

STOS PROGRAM MANAGER - DESIGNATED PERSON
Richard Malott
3840 Ridge Rd
Cleveland, Ohio 44144
634-7111

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:
NAME RICHARD MALOTT SIGNATURE Richard Malott
TITLE EVAL. SPEC. STATE OHIO
CERTIFICATE NUMBER 3012

Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
	S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																		NO NOTICABLE CHANGES ON ACBM OR ASSUMED ACBM

of Material:
- Surfacing Material
- Thermal Insulation
- Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (PRE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. 058
BUILDING NAME Brooklawn Elem
ADDRESS 11801 Worthington
CITY/STATE/ZIP Cleveland, O.

DATE OF REPORT 3/21/97
✓ 13TH Surveillance

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
Richard Malott
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:
NAME RICHARD MALOTT SIGNATURE Richard Malott
TITLE Evaluation Specialist STATE Ohio
CERTIFICATE NUMBER 3012

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
																			No noticable changes in ACBM or assumed ACBM.

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.

ASBESTOS PERIODIC SURVEILLANCE REPORT
TO COMPLY WITH
ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA)

PROJECT NO. #058
BUILDING NAME Brooklawn Elem
ADDRESS 11801 Worthington Ave
CITY/STATE/ZIP Cleveland, Ohio 44111

DATE OF REPORT 3-4-99
9th Year Re-Inspection

ASBESTOS PROGRAM MANAGER - DESIGNATED PERSON
Richard Malott
3840 RIDGE ROAD
CLEVELAND, OHIO 44144

ASBESTOS EVALUATION SPECIALIST RECOMMENDING RESPONSE:
NAME Larry V. Banks SIGNATURE Larry V. Banks
TITLE Evaluation Specialist STATE Ohio
CERTIFICATE NUMBER #3878

14th Surveillance

Room Area No.	Room/Area or Salient ID	Type of Material				Last Report		Change		If Yes		Action Required		Recommended Response					Comments/Project Form No.
		S	T	M	Description	DC	%	Yes	No	DC	%	Yes	No	Cl.	Enc.	Encl.	Rem.	Rep.	
1st	Gym			✓	Ceiling Tile (Mold like substance due to Roof leak & damage)														No changes in ACM or assumed ACBM
					See Attach Report Health Dept														Due to budget constraints, bulk sampling & analysis is limited to damaged assume ACBM

Type of Material:
S - Surfacing Material
T - Thermal Insulation
M - Miscellaneous

Damage Condition (DC):
ND - No Damage
D - Damage
SD - Significant Damage

Recommended Response:
Cl. - Clean
Enc. - Encapsulate
Encl. - Enclose
Rem. - Remove & Replace
Rep. - Repair

* INCLUDE THIS REPORT IN SECTION X OF THE ASBESTOS MANAGEMENT PLAN (RE-INSPECTION & PERIODIC SURVEILLANCE).

The above surveillance report reflects an inspection of all the homogeneous areas within the school. Any changes of the asbestos-containing material shall be reflected above specifying the individual rooms/areas.